



US Army corps Of Engineers Buffalo District 1776 Niagara Street Buffalo, New York 14207-3199

Notice to Navigation Interests

]	L05 - 19
Notice No.	Date
Waterway	

Lake Erie, New York

LRB-ON-TDS

Condition of Federal Navigation Channel Buffalo Harbor, Buffalo, New York

- 1. Condition surveys performed within sections of the Federal navigation Channel at Buffalo Harbor, New York during the months of June 15, 2004 through October 22, 2004 indicate shoaling has reduced depths to those shown on the attached standard tabular form and channel condition drawings.
- 2. Soundings are in feet and referred to Low Water Datum (LWD) 569.2 feet above Mean Water Level (MWL) at Rimouski, Quebec (International Great Lakes Datum 1985).
- 3. Vessel operators are advised to use caution when navigating in this area.
- 4. Copies of the sounding prints for Buffalo Harbor, New York consisting of (3) sheets, 04S-BFH-1/1 through 1/3, at a cost of \$2.50 per sheet will be furnished upon receipt of a check in the full amount made payable to: United States Army Engineer District, Buffalo. Requests should be addressed to: District Commander, U.S. Army Engineer District, Buffalo, ATTN: NY/PA O&M Office, 1776 Niagara Street, Buffalo, New York 14207, requesting exact number or copies of sheets by file number. A point of contact and phone number must be indicated to facilitate response to the request. To obtain the Metadata and CADD files and view a color version of this map, point your web to http://www.lrb.usace.army.mil/waterways/survey/survey.html. Click on the link "SURVEY SECTION" to send a message containing your request
- 5. Buffalo district's point of contact in reference to the exact number of sheets, file number, and the availability of any later information pertaining to the area is Mr. Kelly L. Maccarone, Chief of the Survey Section, Buffalo District, and may be contacted by phone at 716-879-4285.

REPORT OF CHANNEL CONDITIONS (FOR CHANNELS 400 FEET WIDE OR GREATER) (ER-1330-2-316)

PAGE 2 OF 4 PAGES

DATE

TO: ACCOMPANY LOCAL NOTICE TO NAVIGATION INTERESTS, DATED

FROM: U.S. ARMY CORPS OF ENGINEERS, BUFFALO DISTRICT 1776 NIAGARA STREET, BUFFALO, NY 14207-3199 (716) 879-4292 FAX (716) 879-4356

JUNE OCTOBER 2004 JUNE OCTOBER	WIDTH (feet)	LENGTH (feet)	DEPTH (feet)	LEFT OUTSIDE QUARTER (feet)	LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	RIGHT OUTSIDE QUARTER (feet)
OCTOBER 2004 JUNE OCTOBER	1000	2000 (-)		1	2	â	
OCTOBER 2004 JUNE OCTOBER	1000	2000 (-)				3	4
OCTOBER		2000 (a)	30	27.8	28.7	27.6	14.4
2004	1200- 400	1950	29	27.2	26.0	25.2	21.6
JUNE OCTOBER 2004	1100- 1600	3900(b)	28	19.5	24.1	23.9	24.1
JUNE OCTOBER 2004	0-900	4200 (b)	23	19.0	19.2	21.2	22.4
JUNE OCTOBER 2004	500- 1600	11150 (b)	27	21.8	23.4	23.9	22.9
JUNE OCTOBER 2004	800	3000 (b)	25	23.0	24.9	25.0+	24.8
JUNE OCTOBER 2004	1370- 1200	4800 (b)	23	17.6	20.6	20.9	20.7
	SEE LOCAL NOTICE FOR BUFFALO RIVER						
	SEE LOCAL NOTICE FOR BALCK ROCK CANAL						
	1					1	•
(JUNE DCTOBER 2004 JUNE DCTOBER 2004 JUNE DCTOBER 2004 JUNE DCTOBER 2004	JUNE 2004 500- JUNE 2004 500- JUNE 2004 800 JUNE 2004 1370- 1200 SEE LOC FOR BASE	DCTOBER 2004 0-900	DCTOBER 2004 200 (b) 23	DCTOBER 2004 0-900 4200 (b) 23 19.0	DCTOBER 2004 0-900 4200 (b) 23 19.0 19.2	DCTOBER 2004 0-900 4200 (b) 23 19.0 19.2 21.2

REMARKS: (a) LENGTH VARIES DEPENDING ON THE LOCATION OF THE 25 FOOT CONTOUR IN LAKE ERIE.

(b) IRREGULARLY SHAPED, SEE PROJECT CONDITION DRAWINGS.

PAGE 3 OF 4

